

Pre-Qualified Paint Systems - Structure Maintenance Painting

[Back to Approved Lists](#)

Lists of pre-qualified paint sources and systems for structure maintenance painting were previously contained in the below noted Standardized Special Provisions(STSP). STSPs now direct the contractor to the lists contained herein.

Updated: 5-9-2007



STSP Number	Item Number	Description
517-036	517.3000.S	Structure Overcoating Cleaning and Priming, Structure
517-050	517.1800.S	Structure Repainting Recycled Abrasive, Structure



WisDOT LAN users can link to the STSP list on the DOTNET at:

<http://dotnet/dtidcons/constnds/stsp/stsp.htm>

Standardized Special Provisions are available to WisDOT eligible engineering consultants city, county, and municipal staff to download as zipped files on the WisDOT Extranet at:

<https://trust.dot.state.wi.us/extntgtwy/consultants/stsp.htm>

Contact Information:

Bruce Karow

Bureau of Structures

Phone: 608-266-8488

E-Mail: bruce.karow@dot.state.wi.us

Structure Overcoating Cleaning and Priming

Date: 5-14-2007

Solvent Cleaning for Overcoat - Minimal Surface Preparation (SP1)

<u>Manufacturer</u>	<u>System component</u>	<u>Coat</u>
Sherwin- Williams	Corothane I Mastic	1st
	Corothane I Ironox A	2nd
Wasser	MC-Miomastic	1st
	MC-Ferrox A	2nd
Xymax	Mono-Ferro	1st
	Bridge Finish	2nd

Hand Tool Cleaning - Minimal Surface Preparation (Tightly adherent Rust) (SP2) or Power Tool Cleaning - Minimal Surface Preparation (Tightly adherent Rust) (SP3)

<u>Manufacturer</u>	<u>System component</u>	<u>Coat</u>
Sherwin- Williams	Corothane I - Preprime	1st
	Corothane I Mastic	2nd
	Corothane I Ironox A	3rd
Wasser	MC-Prebond	1st
	MC-Miomastic	2nd
	MC-Ferrox A	3rd
Xymax	Mono-Lock P.P.	1st
	Mono-Ferro	2nd
	Bridge Finish	3rd

Power tool Cleaning - Bare Metal (SP11)

<u>Manufacturer</u>	<u>System component</u>	<u>Coat</u>
Sherwin- Williams	Corothane I - Galva-Pac	1st
	Corothane I Mastic	2nd
	Corothane I Ironox A	3rd
Wasser	MC-Miozinc	1st
	MC-Miomastic	2nd
	MC-Ferrox A	3rd
Xymax	MonoZinc 390	1st
	Mono-Ferro	2nd
	Bridge Finish	3rd

Contact Information:

Bruce Karow

Bureau of Structures

Phone: 608-266-3722

E-Mail: bruce.karow@dot.state.wi.us

Structure Repainting Recycled Abrasive Structure

Date: 5/9/2007

<u>Manufacturer</u>	<u>Coat</u>	<u>System component</u>	<u>Minimum Dry Film Thickness- Mils (mm)</u>	<u>Maximum Dry Film Thickness- Mils (mm)</u>
Ameron Protective Coating Division	1st	Amercoat 68HS	3.0 (0.075)	5.0 (0.125)
201 North Berry St.	2nd	Amercoat 399	4.0 (0.100)	8.0 (0.200)
Brea, CA 92621	3rd	Amercoat 450H	3.0 (0.075)	5.0 (0.125)
1-800-344-0025				
Carboline	1st	Carbozinc 859	3.0 (0.075)	5.0 (0.125)
350 Hanley Industrial	2nd	Carbogard 888	3.0 (0.075)	5.0 (0.125)
St. Louis, MO 63144	3rd	Carbothane 133LH	3.0 (0.075)	5.0 (0.125)
1-314-644-1000				
International Paint, Inc	1st	Interzinc 52	3.0 (0.075)	5.0 (0.125)
6001 Antoine Drive	2nd	Interguard 475 HS	4.0 (0.100)	8.0 (0.200)
Houston, TX 77091	3rd	Interthane 870	3.0 (0.075)	5.0 (0.125)
1-920-869-6373				
Sherwin Williams	1st	Zinc Clad III HS	3.0 (0.075)	5.0 (0.125)
1051 Perimeter Drive	2nd	Macropoxy 646	5.0 (0.125)	10.0 (0.250)
Schaumburg, IL 60173	3rd	Acrolon 218 HS	3.0 (0.075)	6.0 (0.150)
1-847-240-1550				
Tnemec	1st	Tnemec-Zinc 90-97	3.0 (0.075)	4.0 (0.100)
6800 Corporate Drive	2nd	F.C. Typoxy, Series 27	4.0 (0.100)	6.0 (0.150)
Kansas City , MO 64120	3rd	Endura Shield. Series 75	3.0 (0.075)	5.0 (0.125)
1-816-483-3400				

Contact Information:
 Bruce Karow
 Bureau of Structures
 Phone: 608-266-3722
 E-Mail:

bruce.karow@dot.state.wi.us